Table 4: Preliminary Analytical Data Summary - Comparison of Concentrations Exceeding Action Levels Puerto Rico Olefins Asbestos Site Peñuelas, Puerto Rico March 4 through 27, 2014

Property No.	Micro Vac Sample Asbestos Type	Micro Vac Concentration (s/cm²)	Air Sample Asbestos Type	Air Concentration (s/cc)	Property Construction Materials	Property Construction Year (approximate)	Closest Wipe Sample
P0006	Chrysotile	14280.7 (MV03-01)	Chrysotile	0.02800 (AS01-030414)	Concrete construction, popcorn ceiling, carpet, gypsum board	Not Available	P0006-WP01 Chrysotile: 32200000 str/cm2
			Chrysotile	0.07220 (AS03-030414)			
P0069	Chrysotile Actinolite	89670.6 (MV01-01)	Chrysotile Anthophyllite Actinolite	0.0047 (AS01-030614)	Wood construction, vinyl tile	1980	P0010-WP01 Chrysotile: 116000 str/cm2
	Chrysotile Actinolite Amosite Chrysotile	15310.3 (MV02-01)	Chrysotile Actinolite	0.001 0 (AS02-030614)			
	Actinolite	5613.8 (MV03-01)					
P0008 (Commercial)	Chrysotile	8140.0 (MV01-01)	Chrysotile Anthophyllite	0.0038 (AS01-030814)	Hardware store, wood construction, vinyl tile, popcorn ceiling	1967	P0008-WP01 Chrysotile: 470000 str/cm2
	Chrysotile	18372.4 (MV02-01)	Chrysotile	0.0346 (AS02-030814)			
	Chrysotile	114171.4 (MV03-01)	Chrysotile	0.0055 (AS03-030814)			
P0008 (Residential)	Chrysotile	12728000.0 (MV01-01)	Chrysotile	0.2097 (AS04-031014)	Concrete construction, ceramic tile, ongoing construction	1970	P0008-WP01 Chrysotile Asbestos: 470000 str/cm2
	Chrysotile	5452.6 (MV02-01)	Chrysotile	0.5299 (AS05-031014)			
	Chrysotile	38480.0 (MV03-01)	Chrysotile	0.1053 (AS06-031014)			
P0186	Chrysotile	93425.0 (MV01-01)	Chrysotile	0.00309 (AS02-032714)	Tire Shop (old gas station), concrete construction, concrete floor	1982	No wipe samples were collected near this property
P0049	NAAL	NAAL	Chrysotile	0.00466 (AS02-032514)	Wood construction, ceramic tile	1980	P0009-WP01 Chrysotile: 485000 str/cm2
P0051	Chrysotile	8880.0 (MV02-01)	NAAL	NAAL	Concrete construction, ceramic tile	2002	P0007-WP01 Chrysotile:
	Chrysotile	6012.5 (MV03-01)					<145000 str/cm2
P0007	Chrysotile	8692.1 (MV03-01)	NAAL	NAAL	Wood construction, vinyl tile	1984	P0007-WP01 Chrysotile: <145000 str/cm2
P0067B	Chrysotile	20473.3 (MV02-01)	NAAL	NAAL	Concrete construction, ceramic floor tile	1964	P0010-WP01 Chrysotile:
	Chrysotile	8633.3 (MV03-01)					116000 str/cm2
P0067A	Chrysotile	16444.4 (MV01-01)	NAAL	NAAL	Concrete construction, ceramic floor tile	1999	P0010-WP01 Chrysotile: 116000 str/cm2

Table 4: Preliminary Analytical Data Summary - Comparison of Concentrations Exceeding Action Levels Puerto Rico Olefins Asbestos Site Peñuelas, Puerto Rico March 4 through 27, 2014

Property No.	Micro Vac Sample Asbestos Type	Micro Vac Concentration (s/cm²)	Air Sample Asbestos Type	Air Concentration (s/cc)	Property Construction Materials	Property Construction Year (approximate)	Closest Wipe Sample
P0056A	Chrysotile	14280.7 (MV02-01)	NAAL	NAAL	Concrete construction, ceramic floor tile	Not Available	P0008-WP01 Chrysotile: 470000 str/cm2
P0005	Chrysotile Actinolite	8140.0 (MV02-01)	NAAL	NAAL	Wood construction, vinyl tile, ceiling panels	Not Available (Trailer)	P0005-WP01 Chrysotile: 8730000 str/cm2
P0057	NAAL	NAAL	Anthophyllite	0.0010 (AS01-030714)	Wood and concrete construction, vinyl tile	Not Available	P0010-WP01 Chrysotile: 116000 str/cm2
P0058	Chrysotile	11737.9 (MV01-01)	NAAL	NAAL	Wood construction, wooden ceiling, vinyl tile	Not Available	P0010-WP01 Chrysotile: 116000 str/cm2
P0187	Chrysotile	7789.5 (MV03-01)	NAAL	NAAL	West Indies Engineering Corp, concrete floor, wood panel walls, ceiling tiles (insulation sampled- was non-detect)	1964	No wipe samples were collected near this property

NAAL - Not Above Action Level

Highlighted samples collected from the five locations properties.

Closest wipe sample column - Data from previous sampling events